- 1. The Reichsbahn branch line from Eisenach to the border town of warthan has been dismentled. A wooden building has been erected on the former right-of-way just inside the border.
- 2. On 4 October 1952, the second track of the Berlin outer freight ring between Seddin and Grossbeeren was again placed in service. A short stretch between Genshagen and Grossbeeren is still single-track because a bridge has not yet been widened.
- The second track on the line between Jüterbog and Grossbeeren, which was to be double-tracked during 1952, can be completed only between Trebbin and Ludwissfelde. Lack of required materials is the cause. A test run on the already-completed stretch with a locomotive of series O3 achieving a speed of 75 miles per hour, rendered the line unserviceable. Poor roadbed caused the rail under the strain to shift in places.
- 4. The second track of the five kilometer stretch between Lannage and Drewitz, restored in 1949, is now again being dismantled in order to provide rail and other materials needed for construction on the new SeBahn Nordring.
- 5. The date for completion of the S-Bahn Nordring between Karow and Birkenwarder has been delayed a second time. Difficulties with ground water are being encountered at Athlenbeck. It is considered impracticable to drain the area because this would so disting the water table as to risk depriving Ethlenbeck of its water supply.
- 6. The Reichsbahn quota for diesel fuel has been cut by 50 vergent effective 1 October 1952, on an order from the East German Ministry of Transport
- 7. The taxes Wargonbau Werdau VEB, at GBrlitch had in lay off mery of its employeds because the plant lacks materials to continue work on construction orders.

C	CLASSIFICATION	SECRET	
STATE # NAVY	NSRB	DISTRIBUTION	
ARMY # AIR #	F 81		

Approved For Release 2006/04/18 : CIA-RDP82-00457R015000260010-0

Frankfurt/Oder. Most of these were enroute to Prenzlau.

23	Soviet military directaft entering or leaving East Germany by rail through
	Frankfurt/Oder are always packed in wooden cases. They are usually
	haded on a or S flatcars and generally exceed the normally bermitted
	measurement limits for standard right-of-way clearance.

25X1

25X1

SECRET